



CERTIFICATE OF COMPLIANCE

CERTIFICATE NUMBER: 061000-R18465

ISSUE DATE: October 6, 2000

Page 1 of 1

Issued to: Zero International Inc.
415 Concord Avenue
Bronx, NY 10455

Report Reference: R18465


This is to Certify that
representative samples of: FS1001, FS2002, FS3003, FS4004 Type Intumescent

Have been investigated by Underwriters Laboratories Inc.* in accordance with the Standard(s)
indicated on this Certificate.

Standard(s) for Safety: UL10C - Standard for Positive Pressure Fire Tests of Door Assemblies
UBC 7-2 (1997) - Fire Test of Door Assemblies


Additional Information: Fire Door Accessories: 557FS/56FS, 59FS, 159FS, 155FS/555FS
3056FS, 3557FS, 58FS, 253FS, 302FS, 328FS

Only those products bearing the UL Classification Marking should be considered as being
covered by UL's Classification and Follow-Up Service.


The UL Classification Marking includes: UL in a circle symbol:  with the word "CLASSIFIED" (as shown); a control number
(may be alphanumeric) assigned by UL; a statement to indicate the extent of UL's evaluation of the product; and, the product
category name (product identity) as indicated in the appropriate UL Directory.

LOOK FOR THE UL CLASSIFICATION MARKING ON THE PRODUCT

Engineer:


Howard J. Gruszynski
Underwriters Laboratories Inc.

Review Engineer:


Daniel J. Kaiser
Underwriters Laboratories Inc.